



**Figure 2-10**  
**Mile 98 Sibley Point Bar**

Sibley Arroyo deposits sediment within the river that has been periodically dredged. The eastern side of the river supports a point bar opposite the mouth of Sibley Arroyo at mile 98.

**Integrated USIBWC Land Management Alternative**

<i>Point Project Measures</i>	ID	#	Area (ac)
Bank shave downs*	98B	1	4.1

**Targeted River Restoration Alternative**

<i>Point Project Measures</i>	ID	#	Area (ac)
Modify dredging at arroyos by creating embayments	98D	1	0.27

\* Bank shave downs acreage is included in the Targeted River Restoration Alternative as a linear measure "Seasonal peak flows".

